

postal mail also will be posted to www.regulations.gov. If you do not want your personal contact information to be publicly viewable, do not include it in your comment or any accompanying documents. Instead, provide your contact information in a cover letter. Include your first and last names, email address, telephone number, and optional mailing address. The cover letter will not be publicly viewable as long as it does not include any comments.

Include contact information each time you submit comments, data, documents, and other information to DOE. If you submit via postal mail or hand delivery/courier, please provide all items on a CD, if feasible, in which case it is not necessary to submit printed copies. No telefacsimiles (“faxes”) will be accepted.

Comments, data, and other information submitted to DOE electronically should be provided in PDF (preferred), Microsoft Word or Excel, WordPerfect, or text (ASCII) file format. Provide documents that are not secured, that are written in English, and that are free of any defects or viruses. Documents should not contain special characters or any form of encryption and, if possible, they should carry the electronic signature of the author.

Campaign form letters. Please submit campaign form letters by the originating organization in batches of between 50 to 500 form letters per PDF or as one form letter with a list of supporters’ names compiled into one or more PDFs. This reduces comment processing and posting time.

Confidential Business Information. Pursuant to 10 CFR 1004.11, any person submitting information that he or she believes to be confidential and exempt by law from public disclosure should submit via email two well-marked copies: one copy of the document marked “confidential” including all the information believed to be confidential, and one copy of the document marked “non-confidential” with the information believed to be confidential deleted. DOE will make its own determination about the confidential status of the information and treat it according to its determination.

It is DOE’s policy that all comments may be included in the public docket, without change and as received, including any personal information provided in the comments (except information deemed to be exempt from public disclosure).

V. Approval of the Office of the Secretary

The Secretary of Energy has approved publication of this notification of data availability and request for comment.

Signing Authority

This document of the Department of Energy was signed on July 18, 2024, by Jeffrey Marootian Principal Deputy Assistant Secretary for Energy Efficiency and Renewable Energy, pursuant to delegated authority from the Secretary of Energy. That document with the original signature and date is maintained by DOE. For administrative purposes only, and in compliance with requirements of the Office of the Federal Register, the undersigned DOE Federal Register Liaison Officer has been authorized to sign and submit the document in electronic format for publication, as an official document of the Department of Energy. This administrative process in no way alters the legal effect of this document upon publication in the **Federal Register**.

Signed in Washington, DC, on July 18, 2024.

Treana V. Garrett,

Federal Register Liaison Officer, U.S. Department of Energy.

[FR Doc. 2024–16177 Filed 7–19–24; 4:15 pm]

BILLING CODE 6450–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2024–1892; Project Identifier MCAI–2024–00198–T]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2023–07–13, which applies to certain Airbus SAS Model A350–941 and –1041 airplanes. AD 2023–07–13 requires repetitive detailed inspections of the lower attachment studs on the AFT galley complex and, depending on findings, replacement of the lower attachment studs. Since the FAA issued AD 2023–07–13, it has been determined that additional airplanes are affected, and that all affected parts must be replaced with serviceable parts. This

proposed AD would continue to require the actions in AD 2023–07–13, add airplanes to the applicability, and require the replacement of all affected parts, as specified in European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by September 6, 2024.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](http://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](http://www.regulations.gov) under Docket No. FAA–2024–1892; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website ad.easa.europa.eu. It is also available at [regulations.gov](http://www.regulations.gov) under Docket No. FAA–2024–1892.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT: Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email dat.v.le@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or

arguments about this proposal. Send your comments to an address listed under **ADDRESSES** section. Include “Docket No. FAA–2024–1892; Project Identifier MCAI–2024–00198–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email dat.v.le@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2023–07–13, Amendment 39–22415 (88 FR 31169, May 16, 2023) (AD 2023–07–13), for certain Airbus SAS Model A350–941 and –1041 airplanes. AD 2023–07–13 was prompted by an MCAI originated by EASA, which is the Technical Agent for the Member States of the European Union. EASA issued AD 2022–0196, dated September 20, 2022, to correct an unsafe condition.

AD 2023–07–13 requires repetitive detailed inspections of the lower

attachment studs on the AFT galley complex for damage (*i.e.*, stress marks, dents, bumps, corrosion, contamination, cracks, and scratches) and correct installation and, depending on findings, replacement of the lower attachment stud. The FAA issued AD 2023–07–13 to address broken lower attachment studs having Part Number (P/N) XP14–070–007800 on the AFT galley complex. The manufacturer’s investigation indicates that the broken lower attachment studs having P/N XP14–070–007800 resulted from a hydrogen-induced failure. The unsafe condition, if not addressed, could lead to galley module detachment, resulting in injury to airplane occupants and reduced capacity for emergency evacuation of the airplane.

Actions Since AD 2023–07–13 Was Issued

The preamble to AD 2023–07–13 explains that the FAA considers the requirements “interim action” and was considering further rulemaking. The FAA has now determined that further rulemaking is indeed necessary, and this proposed AD follows from that determination.

Since the FAA issued AD 2023–07–13, EASA superseded AD 2022–0196, dated September 20, 2022, and issued EASA AD 2024–0078, dated March 20, 2024 (EASA AD 2024–0078) (also referred to as the MCAI), to correct an unsafe condition for certain Airbus SAS Model A350–941 and –1041 airplanes. The MCAI states that additional airplanes are affected, and that all lower attachment studs having P/N XP14–070–007800, on the AFT galley complex must be replaced. Broken lower attachment studs on the AFT galley complex, if not addressed, could lead to galley detachment, resulting in injury to airplane occupants and reduced capacity for emergency evacuation of the airplane.

The FAA is proposing this AD to address the unsafe condition on these products. You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2024–1892.

Explanation of Retained Requirements

Although this proposed AD does not explicitly restate the requirements of AD 2023–07–13, this proposed AD would retain all of the requirements of AD 2023–07–13. Those requirements are referenced in EASA AD 2024–0078, which, in turn, is referenced in paragraph (g) of this proposed AD.

Material Incorporated by Reference Under 1 CFR Part 51

EASA AD 2024–0078 specifies repetitive detailed inspections for damaged and incorrectly installed lower attachment studs having P/N XP14–070–007800 on the AFT galley complex and, depending on findings, replacement of the lower attachment studs, and eventual replacement of all affected lower attachment studs having P/N XP14–070–007800. The MCAI specifies that replacement of all lower attachment studs having P/N XP14–070–007800 on all affected AFT galleys constitutes a terminating action for the repetitive detailed inspections.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2024–0078 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2024–0078 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2024–0078 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in

EASA AD 2024–0078 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled

“Required Action(s) and Compliance Time(s)” in EASA AD 2024–0078. Material required by EASA AD 2024–0078 for compliance will be available at *regulations.gov* under Docket No. FAA–2024–1892 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 13 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained actions from AD 2023–07–13	2 work-hours × \$85 per hour = \$170	\$0	\$170	\$2,210
New proposed actions	7 work-hours × \$85 per hour = \$595	95	690	8,970

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing airworthiness directive 2023–07–13, Amendment 39–22415 (88 FR 31169, May 16, 2023); and
 - b. Adding the following new airworthiness directive:

Airbus SAS: Docket No. FAA–2024–1892; Project Identifier MCAI–2024–00198–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by September 6, 2024.

(b) Affected ADs

This AD replaces AD 2023–07–13, Amendment 39–22415 (88 FR 31169, May 16, 2023) (AD 2023–07–13).

(c) Applicability

This AD applies to Airbus SAS Model A350–941 and –1041 airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2024–0078, dated March 20, 2024 (EASA AD 2024–0078).

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

(e) Unsafe Condition

This AD was prompted by reports of broken lower attachment studs having P/N XP14–070–007800 on the AFT galley complex. The FAA is issuing this AD to address broken lower attachment studs having XP14–070–007800 on the AFT galley complex. The unsafe condition, if not addressed, could lead to galley module detachment, resulting in injury to airplane

occupants and reduced capacity for emergency evacuation of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2024–0078.

(h) Exceptions to EASA AD 2024–0078

(1) Where EASA AD 2024–0078 refers to “04 October 2022 [the effective date of EASA AD 2022–0196],” this AD requires using June 20, 2023 (the effective date of AD 2023–07–13).

(2) Where EASA AD 2024–0078 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where paragraphs (1), (2), (3), and (4) of EASA AD 2024–0078 specify actions “in accordance with approved instructions issued by Airbus DOA,” this AD requires replacing that text with “in accordance with approved instructions issued by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.”

(3) This AD does not adopt the “Remarks” section of EASA AD 2024–0078.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(ii) AMOCs approved previously for AD 2023–07–13 are approved as AMOCs for the

corresponding provisions of EASA AD 2024–0078 that are required by paragraph (g) of this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (i)(2) of this AD, if any material contains paragraphs that are labeled as RC, the instructions in RC paragraphs, including subparagraphs under an RC paragraph, must be done to comply with this AD; any paragraphs, including subparagraphs under those paragraphs, that are not identified as RC are recommended. The instructions in paragraphs, including subparagraphs under those paragraphs, not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the instructions identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to instructions identified as RC require approval of an AMOC.

(j) Additional Information

For more information about this AD, contact Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email dat.v.le@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2024–0078, dated March 20, 2024.

(ii) [Reserved]

(3) For EASA AD 2024–0078, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locationsoremailfr.inspection@nara.gov.

Issued on July 16, 2024.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024–15958 Filed 7–22–24; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF LABOR

Occupational Safety and Health Administration

29 CFR Part 1910

[Docket No. OSHA–2007–0073]

RIN 1218–AC91

Emergency Response Standard

AGENCY: Occupational Safety and Health Administration (OSHA), Labor.

ACTION: Proposed rule; notice of informal hearing.

SUMMARY: OSHA is scheduling an informal public hearing on its proposed rule “Emergency Response Standard.” The public hearing will begin November 12, 2024, at 9:30 a.m. Eastern Time (ET). The proposed rule was published in the **Federal Register** on February 5, 2024. The initial public comment period was scheduled to end May 6, 2024, but was extended to June 21, 2024, in response to numerous requests from the public. The comment period was extended again, until July 22, 2024, due to more extension requests from stakeholders.

DATES: *Informal public hearing:* The hearing will be held virtually and will begin November 12, 2024, at 9:30 a.m. ET. If necessary, the hearing will continue from 9:30 a.m. until 4:30 p.m., ET, on subsequent weekdays. Additional information on how to access the informal hearing will be posted at <https://www.osha.gov/emergencyresponse/rulemaking>. To testify or question other witnesses at the hearing, interested persons must electronically submit a Notice of Intention to Appear (NOITA) on or before September 27, 2024. In addition, those who request more than 10 minutes for their presentation at the informal hearing and those who intend to submit documentary evidence at the hearing must submit the full text of their testimony, as well as a copy of any documentary evidence, no later than October 18, 2024.

ADDRESSES: *Notice of Intention to Appear (NOITA).* A NOITA must be submitted electronically at: <https://www.osha.gov/emergency-response/rulemaking>. Follow the instructions online for making electronic

submissions. Those who file NOITAs must also submit electronic copies of all documents that they intend to use or reference during their testimony. Information about how and when to submit these materials will be provided at the time of registration.

Instructions: All submissions must include the agency's name and the docket number for this rulemaking (Docket No. OSHA–2007–0073). All comments, including any personal information you provide, are placed in the public docket without change and may be made available online at <https://www.regulations.gov>. Therefore, OSHA cautions commenters about submitting information they do not want made available to the public, or submitting materials that contain personal information (either about themselves or others), such as Social Security Numbers and birthdates.

Docket: To read or download comments and other materials submitted in the docket, go to Docket No. OSHA–2007–0073 at <https://www.regulations.gov>. All comments and submissions are listed in the <https://www.regulations.gov> index; however, some information (e.g., copyrighted material) is not publicly available to read or download through that website. All comments and submissions, including copyrighted material, are available for inspection through the OSHA Docket Office.

FOR FURTHER INFORMATION CONTACT:

For press inquiries: Contact Frank Meilinger, Director, Office of Communications, Occupational Safety and Health Administration, U.S. Department of Labor; telephone: (202) 693–1999; email: Meilinger.Francis@dol.gov.

For general information and technical inquiries: Contact Mark Hagemann, Director, Office of Safety Systems, Directorate of Standards and Guidance, Occupational Safety and Health Administration, U.S. Department of Labor; telephone: (202) 693–2222; email: OSHA.Emergency.Response@dol.gov.

For hearing inquiries: Contact Kathryn Marlor, Directorate of Standards and Guidance, Occupational Safety and Health Administration, U.S. Department of Labor; telephone: (202) 693–2222; email: OSHA.Emergency.Response@dol.gov.

For ASL interpretation and language translation service requests: Contact Kathryn Marlor, Directorate of Standards and Guidance, Occupational Safety and Health Administration, U.S. Department of Labor; telephone: (202) 693–2222; email: OSHA.Emergency.Response@dol.gov.